

To: Kevin Shaver (kshaver@gesoncall.com)[kshaver@gesoncall.com];
djohnson@gesoncall.com[djohnson@gesoncall.com]; Richard Cole
(rcole@gesoncall.com)[rcole@gesoncall.com]
From: Daly, Eric
Sent: Fri 5/13/2016 1:45:28 PM
Subject: HTC-5374 Roberts Street
5374 Roberts Street Building Basement Footprint 05-13-16.pdf

Figure attached.

Good Morning:

Below are the answers to the radon system installer. I have attached a basic footprint map of the basement. However, Peter will be providing us a map with measurements shortly.

- Basement is all concrete
- Sump is concrete with drain tile in floor draining to sump area
- Basement has been dry
- There is no gaps between basement flooring and upright walls
- There are a few settlement cracks that exists in floor and walls
- No Radiant heat in flooring in basement
- The new addition/family room is built on a surrounding footer on 2x12 floor joists

Regards,

Eric

"We must, indeed, all hang together, or assuredly we shall all hang separately", Benjamin Franklin

Eric M. Daly

On-Scene Coordinator/Radiological Response Specialist

US Environmental Protection Agency- Region II

ERRD/RPB/PPS

2890 Woodbridge Avenue

Edison, NJ 08837

daly.eric@epa.gov

732-321-4350